## **STANLEY**

# MHP3 TRACHORSE



### **FEATURES:**

- Self-Propelled Mobile hydraulic tool and equipment carrier that transports tools and equipment in most job-site environments.
- Simple Operating Controls Allows for a wide range of applications.
- Two Speed Forward Track Drive Single Low Reverse Speed.
- Work Lights.
- Opening Tailgate.
- Auxiliary Hydraulic Tool Circuit Is designed for continuous-duty applications and features the standard high-effi ciency cooling found on all Stanley hydraulic power units.
- Climbs 60% grade.
- Carries 1,000 lbs / 454 kg.

#### **SPECIFICATIONS**

1000 lbs
454 kg
2000 psi
38 bar
2 @ 5 gpm or 1 @ 10
gpm
2-20 lpm or 1-38 lpm
1.55 mph - 2.8 mph
2.5 km/h - 4.5 km/h
3 gallons
11 liters
7 gallons
26.5 liters
1200 lbs
544 kg
78 inches
198 cm
36 inches
92 cm
43 inches
109 cm
Honda 20 hp OHV
Flush-Face
Couplers

NEED TO RUN TWO 5GPM TOOLS AT ONCE? ANSWER - GTR20 -THE POWER OF HYDRAULICS

## **STANLEY**

# MHP3 TRACHORSE

### ORDERING INFORMATION

MODEL	PART NO.	DESCRIPTION
МНР3	MHP32242100	Trachorse Dual Circuit, Honda
	MHP32232100	Trachorse Dual Circuit, Honda, Bedless
	MHP32242100U	Trachorse Dual Circuit, Honda - UPRR

### **ACCESSORIES**

ITEM NO.	DESCRIPTION
31848	Dual Hose, 50 ft x 1/2 in., w/couplers
31972	Dual Hose, 25 ft x 1/2 in., w/couplers
03971	HTMA Flush-Face Coupler 3/8 " NPT Brunning
03974	HTMA Flush-Face Coupler 1/2 " NPT Brunning
47438	HTMA Flush-Face Coupler 3/8 " NPT Aeroquip
47441	HTMA Flush-Face Coupler 1/2 " NPT Aeroquip
35907	Hose Reel Attachment Kit
36138	Hose Reel No Hose
58448	Hose Assy, Dual 50' W/Couplers
58451	Hose Assy, Dual 25' W/Couplers
69760	Diesel Hose Reel
69529	Gas Hose Reel



#### **WARRANTY:**

Stanley Hydraulic Tools and their associated parts are warranted against defects in materials and workmanship for a period of twelve months from the date of purchase. Stanley Hydraulic Tools reserves the right to repair or replace only those parts which prove to have been defective at the time of purchase. This warranty becomes void if maximum flow and pressure ratings are exceeded.